


Mullewa, Our Lady of Mount Carmel and the Holy Apostles SS. Peter and Paul

8 Doney Street, 6630 Mullewa, Australia



Builder	Positive Organ Company
Year	1927
Period/Style	Classical
Stops	6
Keyboards	1
Keyaction	tracker/mechanical
Tuning	Equal at 440 Hz

Description

The pipework of the organ is damaged (both the visible squashed display pipes and a number of other pipes laying on the floor behind the organ) and the blower system is both non-functional and antiquated. The main trunking from the blower to the organ is through terracotta pipes some 25 metres away from the building, and many of the pipes are broken.

Stoplist/Disposition

Manual

Open Diapason 8'

Stopped Flute 8'

Viole d'Orchestre 8'

Melodic Flute 16'

Melodic Viole 8'

Tremulant

Additional: Octave Coupler

Sources

<http://www.oswa.org.au/sup/WAOrgans/Mullewa/MullewaMtCarmel.html>